



LOTUS SERVICE BULLETIN

Class	III
Number	1970/4
Type	Europa
Date	1.1.1970

LOTUS CARS (SERVICE) Ltd NORWICH NORFOLK NOR92W Tel: WYMONDHAM 3411 CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman				
------------------	-----------------	--	---------	--	--	--	--

Title: Bonnet Lifting.

Reason: To clarify the reason for fixing the reinforcing strip to the trailing edge as detailed in our previous Service Bulletin 1969/40 and 033 (Federal).

Parts Required: -

Price: -

Fitting Time: -

Charges:

U.K.	-	Warranty.....NO
EXPORT	-	Factory.....NO
	-	Distributor.....NO

Action: It should be noted that there is no question of the bonnet lid opening at high speed. At these speeds a pressure differential occurs above and below the bonnet and, owing to flexing of the bonnet panel and rear flange, the rear corners of the bonnet oscillate.

Since the publication of Service Bulletins 1969/40 and 033 (Federal) this modification has been introduced into production at Chassis No. 2640.