



# Lotus Service Bulletin

CLASS: 111  
NUMBER: 1972/2  
TYPE: Europa Twin Cam  
Date: 01.05.72

LOTUS CARS Ltd - NORWICH NORFOLK NOR92W - Tel: WYMONDHAM 3411 - CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman			
------------------	-----------------	--	---------	--	--	--

Title: Inboard Drive Shaft Retaining Pins (Type 352 Transmission only).

Reason: To give an improved method of securing the inboard drive shafts to the transmission output shafts.

Parts Required: Pin, drive shaft A074 F 6013Z 2 off

Charges: U.K. ONLY - Warranty .....20 minutes per car.

- Action:
1. At, or before the next Service due to the car, the following action should be taken.
  2. Remove existing drive shaft retaining pins (see Europa Workshop Manual) and discard.
  3. Fit new pins, driving fully home.
  4. All cars NOT listed have already had this type of pin fitted at the Factory.

Cars affected are:-

2177	2203 to 2279 inc.	0411	1459	1477
2178	2281	0428	1464	1480
2182	1005 to 1008 inc.	0226	1466	1483 to 1556 inc.
2185	1028 to 1030 inc.	1432	1471	
2191	1032	1443	1474	
2192	1034 to 1051 inc.	1445	1475	

NOTE: Distribution of cars are given overleaf. Normal Warranty Claims, marked 'Europa Twin Cam, 1972/2 Class 11', bearing the chassis number of the car should be submitted on completion of the above.

