



LOTUS SERVICE BULLETIN

Class	III
Number	1970/13
Type	Europa
Date	1.4.1970.

LOTUS CARS (SERVICE) Ltd NORWICH NORFOLK NOR92W Tel: WYMONDHAM 3411 CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman				
------------------	-----------------	--	---------	--	--	--	--

Title: Radiator Cooling Fan.

Reason: Introduction of a new cooling fan, with reversed blade pitch, from Chassis No. 7003070089Q.

Parts Required: Fan, Radiator Cooling Part No. A054 K 6002

Price: A054 K 6002 £1. 14. 0d. (£1.70 new pence) each U.K. recommended retail.

Fitting Time: 30 minutes.

Charges:

- U.K. - Warranty.....NO
- EXPORT - Factory.....NO
- Distributor..... NO

Action: Since the fan has blades of reversed pitch, to maintain the same direction of air flow the direction of rotation must be reversed. Therefore, when fitting the new fan, which is interchangeable with the earlier one, the motor connections to the fan relay must be reversed to conform with Fig.1. By operating the heater/cooling switch on the facia, check that the airflow is correct, i.e. is blown onto the front wheel. The new fan is easily distinguished from the earlier one by the shape of its blades which are rectangular and narrow. Consult the Workshop Manual, Section K.7, for instruction on changing the fan.

12th. May, 1970.

ERRATUM: - To Service Bulletin 1970/13 Class III, Radiator Cooling Fan.

The Figure below was inadvertently omitted from this Bulletin.
Please attach Fig.1 to your copy of the Bulletin.




Fig. 1.