



LOTUS SERVICE BULLETIN

Class	III
Number	1970/28
Type	Europa, ElanD/H
Date	1.7.1970

LOTUS CARS (SERVICE) Ltd NORWICH NORFOLK NOR92W Tel: WYMONDHAM 3411 CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman				
------------------	-----------------	--	---------	--	--	--	--

Title: Interior Mirror.

Reason: Better adhesive, providing more security.

Parts Required: 'Loctite 312' Adhesive Part No. A036 B 6252

Charges:

U.K.	-	WarrantyNO
EXPORT	-	FactoryNO
	-	DistributorNO

Action: The new adhesive was introduced into current Production during May 1970 as a running change and no chassis numbers are available. When and/or if an interior mirror becomes detached from its location, 'Loctite 312' should be used to refix the mirror.

When using 'Loctite 312' it is important to follow the manufacturers instructions which will be found on the container.