



# Lotus Service Bulletin

CLASS: 111  
NUMBER: 1973/13  
TYPE: All Europa  
Date: 20.07.73

LOTUS CARS Ltd - NORWICH NORFOLK NOR92W - Tel: WYMONDHAM 3411 - CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman			
------------------	-----------------	--	---------	--	--	--

Title: Fan Motor Protection.

Reason: To advise Dealer personnel of the approved method of water deflection.

Parts Required:	A074 M 0228Z	Shield, fan motor	1 off
	313AA	Screw	2 off
	A075 W 6013Z	Spire nut	2 off

Action: In cases of persistent complaints of rain water (or other water) being channeled on to the radiator cooling fan motor, via the front compartment drip gutter, it is recommended that the following action be taken.

1. Using the illustration as a guide, fit the shield, retaining it with the screws and spire nuts.

