



Lotus Service Bulletin

CLASS: 111
NUMBER: 1972/02
TYPE: Europa Twin Cam
Date: 21.07.1972

LOTUS CARS Ltd - NORWICH NORFOLK NOR92W - Tel: WYMONDHAM 3411 - CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman			
------------------	-----------------	--	---------	--	--	--

Title: Servo Units Vacuum Hoses Connection.

Reason: To introduce an improved connection between servo units and their vacuum hoses.

Parts Required: 'T' piece A704 J 6040Z 1 off
Clip A704 J 6041Z 3 off
These will be supplied F.O.C. to Distributors.

Action:

1. At, or before the next Service due to the car, the following action should be taken.
2. Remove the existing nylon 'T' piece (Part No. X050 J 6058Z) interconnecting the three vacuum hoses, and discard.
3. Fit the new metal 'T' piece to connect the three vacuum hoses together, securing with the clips (see illustration).

