



# LOTUS SERVICE BULLETIN

Class	III
Number	1970/26
Type	All models
Date	1.7.1970

LOTUS CARS (SERVICE) Ltd NORWICH NORFOLK NOR92W Tel: WYMONDHAM 3411 CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman				
------------------	-----------------	--	---------	--	--	--	--

**Title:** Fuel Tank Sender Unit Special Locking Tool.

**Reason:** Introduction of Special Tool to ensure that when tank sender units are checked for leaks, or replaced, they can be fully tightened.

**Parts Required:** Sender Unit Special Tool Part No. A036 T 6015

**Price:** A036 T 6015 19s. 3d. (96p.) U.K. recommended retail

**Charges:**

U.K.	- Warranty.....	NO
EXPORT	- Factory .....	NO
	- Distributor .....	NO

**Action:** When the occasion arises (i.e. replacement or, when checking the fuel system for leaks on the P.D.I.), use the Special Tool to check that the fuel tank sender unit is fully tightened and thus, not leaking.