



LOTUS SERVICE BULLETIN

Class	III
Number	1970/6
Issue	Issue 2
Type	All Models
Date	28.1.1970

LOTUS CARS (SERVICE) Ltd NORWICH NORFOLK NOR92W Tel: WYMONDHAM 3411 CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman				
------------------	-----------------	--	---------	--	--	--	--

Title: Tyre Pressures.

Reason: The recommended tyre pressures have been changed on all models.

Charges: U.K. - Warranty.....NO
 EXPORT - Factory.....NO
 - Distributor.....NO

Action: The new recommended COLD tyre inflation pressures are as follows:

MODEL	AT SPEEDS BELOW 100 m.p.h. (160 k.p.h.)		AT SUSTAINED SPEEDS ABOVE 100 m.p.h. (160 k.p.h.)	
	Front	Rear	Front	Rear
ELAN	181bs.in. ² (1.27 kg.cm. ²)	231bs.in. ² (1.62 kg.cm. ²)	241bs.in. ² (1.69 kg.cm. ²)	291bs.in. ² (2.04 kg.cm. ²)
ELAN + 2	201bs.in. ² (1.41 kg.cm. ²)	241bs.in. ² (1.69 kg.cm. ²)	261bs.in. ² (1.83 kg.cm. ²)	301b.in. ² (2.11 kg.cm. ²)
EUROPA	181bs.in. ² (1.27 kg.cm. ²)	281bs.in. ² (1.97 kg.cm. ²)	241bs.in. ² (1.69 kg.cm. ²)	341bs.in. ² (2.39 kg.cm. ²)

Would you please amend your Service literature to incorporate this information. The new pressures are suitable for cars in the maximum loaded condition. It is NOT necessary to increase the pressures for any condition other than sustained speeds above 100 m.p.h. (160 k.p.h.) as given above, this of course only applies anyway to countries where high road speeds are within the legal limit.