

Lotus Service Bulletin

CLASS: 111

NUMBER: 1973/04 TYPE: All Europa Date: 28.02.1973

LOTUS CARS Ltd - NORWICH NORFOLK NOR92W - Tel: WYMONDHAM 3411 - CABLES LOTUS NORWICH TELEX 97401

| Circulation List Service Manager | | Foreman | | | |
|------------------------------------|--|---------|--|--|--|
|------------------------------------|--|---------|--|--|--|

Title: Door Hinge Bobbins.

Reason: To advise Dealers of a revised method of fitting the upper door hinges.

Action: If reference is made to the illustration, it will be seen that the upper abrasive washer on the upper door hinge bobbin, has been deleted. The new assembly method is shown below, whereas the previous assembly method is shown in Fig. 23 on Page 39 of Section 'B' (Body), of the Europa Workshop Manual (X046 T 0327Z).

When the occasion arises to refit the door hinge, it is recommended that the spacer (128D) is tack-welded to the bobbin as shown. This will make the bobbin easier to fit, and give an overall saving in fitting time of approximately 20 minutes.

