

LOTUS EUROPA TWINCAM PARTS CROSSREFERENCE

May 1976 Edition

<u>DESCRIPTION</u>	<u>PARTS BOOK REF NUM</u>	<u>PART NUMBER</u>	<u>SOURCE</u>
ENGINE:			
Engine Mounting	EA 33	A074E0549Z	1967-69 Cortina F208
Assembly, Flywheel	EB 25	A026E0717W	RING GEAR ONLY- Ford 105E 6384
Assembly, Oil Pump	EC 1	A036E6029W	REBUILD KIT- Ford 105E 6608
Assembly, Oil Filter	EC 3	A036E6030W	PER 64, LEE 64, FRAM CH 855 APL, Ford 113E 6731 A, WIX 51327, TECALEMIT FP 3347, ROYZE RP 52
Oil Pump Gasket	EE 28	A026E0325Z	Ford 3020E 6789A
Oil Pump Assembly from Ford 1600 Pinto engine will replace any Twincam oil pump and will provide higher pressure and flow rate. Ford part no. D1FZ 6600 C. Takes spin-on replaceable filter.			
Assembly, Fuel Pump	EH	X026E0370W	REBUILD KIT- EFFBE SDE 87 (FOREIGN CAR PARTS CO., TEMPLE CITY)
Motor, Starter Starter Pinion Drive-Complete -Outer Barrel & Pinion Only	MA 7	A077E6010Z	LUCAS 54252212-B1262 LUCAS 250698-B1260
Distributor Cap	MA 9	X028M0073Z	LUCAS 54412472-B1373
Rotor Arm	MA 9	X028M0070Z	LUCAS 54412165, Non-cutout : SORENSEN- CORTINA G-41
Contact Set, (Quick Fit)	MA 9	A036M6362Z	LUCAS 54413568, SORENSEN-CORTINA G-145
Alternator Belt	MA 15	A074E6008Z	GOODYEAR 13T291
Cam Cover Gasket			Ford 3020E 6K260A (Villa Ford, Orange, CA)

<u>DESCRIPTION</u>	<u>PARTS BOOK REF NUM</u>	<u>PART NUMBER</u>	<u>SOURCE</u>
L/H Vertical Link	CA 1	X036C6006Z	Spitfire
R/H " "	"	X036C6005Z	"
Stub Axle	"	X036C6008Z	Spitfire
Nut	"	X036C6033Z	"
Washer	"	X036C6034Z	"
L/H Caliper Mounting Plate	CA 2	X036C6022Z	Spitfire
R/H " "	"	X036C6021Z	"
Ball Joint Assembly	CA 3	X036C6007Z	Spitfire
Nut, Attaching	"	218	"
L/H Lower Trunnion Assembly	CA 4	X036C6026W	Spitfire
R/H " " "	"	X036C6025W	"
Seal	CA 7	X036C6028Z	Spitfire
L/H Steering Arm	CA 8	X036H6001Z	Spitfire
R/H " "	"	X036H6000Z	"
Hub	CA 9	X036C6014Z	Spitfire
Wheel Stud	"	X036C6015Z	"
Wheel Bearing, Outer	CA 10	X036C6016Z	Spitfire, also: U Timken 03062
" " , Inner	CA11	X036C6017Z	" , also: Y Timken 07210X
"D" Washer, Hub to Stub Axle	CA 12	X036C6009Z	Spitfire
Nut, Castellated	CA 13	X036C6010Z	"
Split Pin	"	W0087	"
Oil Seal	CA 14	X036C6018Z	"
Grease Cap	CA 15	X036C6013Z	"
Brake Disc	CA 16	X036J6008Z	Spitfire
Bolt, Attaching	"	X036J6009Z	"
Washer		X036J6010Z	"

<u>DESCRIPTION</u>	<u>PARTS BOOK REF NUM</u>	<u>PART NUMBER</u>	<u>SOURCE</u>
L/H Dust Cover	CA 17	X036C6020Z	Spitfire
R/H " "	"	X036C6019Z	"
Bolt, Dust Cover/Caliper Mounting	"	X036C6023Z	"
Bolt, Dust Cover/Caliper Mounting Plate/Steering Arm Attaching	"	X036C6024Z	"
Nut	"	215	"
Damper/Spring Assembly	CA 27	A074C0730W	Shock only: Koni 8212-1088B (Racing)
<b>REAR SUSPENSION</b>			
Damper Assembly	DA 25	A074D6007W	Koni 8212-1177B (Racing)
Universal Joint	DA 9	A074D6008Z	AEC Number 344, Republic No. CB-1250B
Hose, Flexible, Rear	JB 21	X046J6020Z	Plymouth Cricket, Part No. 71244109
Caliper Repair Kit	JC 5	X036J6003Z	Girling SP2697
Brake Shoe	JD 2	X046J6002Z	Triumph GT6 Rear
Cylinder Servicing Kit	JD 7	A074J6044Z	" " "
		X046J6006Z	Girling SP2027/4
<b>CLUTCH/TRANSMISSION</b>			
Clutch Release Bearing	QA 6	A074Q6011Z	Cortina-Ford 3014E-7548-C
Gearbox Assembly	FC	A074F6002W	Renault (Some "Lotus Only" Parts)
Gearbox Assembly 13 mm dia Control Shaft	FD	A074F6003W	Renault (100%)
	"	B074F6003W	" "
Gearbox Assembly	FE	A074F6019Z	Renault (100%)

<u>DESCRIPTION</u>	<u>PARTS BOOK REF NUM</u>	<u>PART NUMBER</u>	<u>SOURCE</u>
Control, Remote, L/H	BD 1	X036B6151W	MGB
" " R/H	"	X036B6152W	"
Pin	BD 2	A036B6257Z	MGB
Flap	"	A036B6256Z	"
Switch, Indicators	HA 4	A036H6078Z	Spitfire
Switch, Dip and Flasher	HA 5	X0466M6183Z	Spitfire
" " " "	"	A036H6075Z	"
" " " "	"	A036H6076Z	"
<b>BODY</b>			
Escutcheon	HA 6	X036H06033Z	Spitfire
Wiper Blade	MG 8	X074Q6011Z	Standard 16 in.
Fan Motor	KA 21	A036K0080Z	Smiths 5761/05
L/H External Door Handle	BD 6	X036B6052W	MGB, Midget, Sprite
R/H " " "	"	X036B6053W	" " "
Gasket, Door Handle, Small	"	X036B6168Z	" " "
" " ", Large	"	X036B6164Z	" " "

74MC083

## MISCELLANEOUS NOTES

1. The front suspension uprights and hubs can be replaced with parts from the Triumph GT6 MKIII to enable the use of its larger 9 ¾ inch diameter brake discs and calipers.
2. For exhaust manifold gaskets, try VW.
3. Ignition key from 1969 Spitfire fits door, trunk key from same car fits bonnet and engine compartment locks.

## RUMORS

1. Fuel pump - Pinto 1600 ?
2. Taillight lenses - appear the same as late E-Jags except Lotus has backup light lenses built in. Are lenses from another Jag ?
3. It appears that all parts ending in "Z" are "outside" parts, but that not all "outside" parts end in "Z". True ?

## COMMENT

The 2nd, 3rd, and 4th characters of the part number indicate the Lotus model the part was first used on. The models are:

Europa--046, 054, 065, 074  
Elan --026, 036, 045  
Elan+2--050  
Europa--075 (Special Federal)

Send all updates, corrections, and comments on Europa Twincam parts interchangeability to :

Merl Thurman  
27 Derow Court  
Sacramento, CA 95833