



LOTUS SERVICE BULLETIN

Class	11
Number	1970/2
Type	ALL
Date	1.3.1970

LOTUS CARS (SERVICE) Ltd NORWICH NORFOLK NOR92W Tel: WYMONDHAM 3411 CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman				
------------------	-----------------	--	---------	--	--	--	--

Title: Brake Pipes.

Reason: Neglect of brake pipes, with consequent brake failure.

Charges: U.K. - Warranty.....NO
 EXPORT - Factory.....NO
 - Distributor.....NO

Action: We have received a report of brake failure which was directly attributable to neglect of the brake pipes. It might reasonably be expected that a good mechanic will inspect all brake pipes whenever he is servicing a car. However, to ensure that this is done, thorough inspection of all brake hydraulic and vacuum pipes and their unions, for condition and security, is to be included in the schedule for all Services immediately, including Pre-Delivery Inspections and initial Free Services.

All relevant Service literature will be amended to include this instruction as and when it is convenient to reprint. Meanwhile, would all Dealers please ensure that their Service Personnel are made aware of the instruction immediately.